

Product Compliance Specialists Ltd The Malthouse, Malthouse Square, Princes Risborough Bucks, HP27 9AZ United Kingdom Tel: +44 1844 273 277 Fax: +44 1844 273 278 www.productcompliancespecialists.com info@productcompliancespecialists.com

Regulatory Update

Argentina – following updated regulations for 5GHz WLAN, and Bluetooth devices, Argentine Authority (CNC) confirms that re-testing is required at time of renewal.

In accordance with "Protocolo de equipos de espectro ensanchado por salto en frecuencia", it has been confirmed that all 5GHz WLAN and Bluetooth 4.0 products will require re-testing at the time of renewal.

 For all devices currently being imported and sold in Argentina, manufacturers must ensure that the 5600 - 5650MHz portion of the 5GHz Band 3 (for all WLAN devices) is disabled* This corresponds to the following channels:

802.11a and 802.11n (HT20): channels 120, 124 and 128

802.11n (HT40): channels 118 and 126

802.11ac (VHT80): channel 122

- 2. For new and renewal applications submitted for local testing, sample requirements remain unchanged. Local labs will simply not perform conformance testing in the 5600 5650MHz portion of 5GHz Band 3
- 3. In addition to 5GHz WLAN devices, all Bluetooth 4.0 radios will need to be re-tested at the time of renewal and in accordance with the new regulation
- 4. All current Approvals remain valid until their expiry

*A frequency notch is required for master devices, for client devices passive scanning only is sufficient.

Doc ref: RU1312004



For additional information on the above article please contact:

Rohit Nanwani Product Compliance Specialists

Email: rohit@productcompliancespecialists.com

Date of Issue: 07 January 2014

Page 2 of 2 Doc ref: RU1312004