

Product Compliance Specialists Ltd The Malthouse, Malthouse Square, Princes Risborough Bucks, HP27 9AZ United Kingdom Tel: +44 1844 273 277 Fax: +44 1844 273 278 www.productcompliancespecialists.com info@productcompliancespecialists.com

Regulatory Update

Argentina – following PCS regulatory update in January 2014 concerning product re-testing at renewal, Argentina Authority have confirmed that 2.4GHz WLAN products will also fall under this requirement.

In summary, in accordance with "Protocolo de equipos de espectro ensanchado por salto en frecuencia", all WLAN (2.4GHz & 5GHz) and Bluetooth 4.0 products will require re-testing at the time of renewal.

 For all devices currently being imported and sold in Argentina, manufacturers must ensure that the 5600 - 5650MHz portion of the 5GHz Band 3 (for all WLAN devices) is disabled* This corresponds to the following channels:

802.11a and 802.11n (HT20): channels 120, 124 and 128

802.11n (HT40): channels 118 and 126

802.11ac (VHT80): channel 122

- 2. For new and renewal applications submitted for local testing, sample requirements remain unchanged. Local labs will simply not perform conformance testing in the 5600 5650MHz portion of 5GHz Band 3
- 3. In addition, all Bluetooth 4.0 and 2.4GHz WLAN radios will need to be retested at the time of renewal and in accordance with the new regulation
- 4. All current Approvals remain valid until their expiry

*A frequency notch is required for master devices, for client devices passive scanning only is sufficient.



For additional information on the above article please contact:

Rohit Nanwani Product Compliance Specialists
Email: rohit@productcompliancespecialists.com

Date of Issue: 26 February 2014

Page 2 of 2 Doc ref: RU1402002